



Galileo 03 Limited

Mynydd Ty-talwyn Energy Park – Environmental Statement Volume III

Appendix 5.2: Coal Mining Risk Assessment

Annex D – Adit Photographs

Project reference: 663870

APPENDIX D ADIT PHOTOGRAPHS

Photo No. 1	Date: 13.07.2023	
South-westerly view into woodlands at the location of Adit 287185-001.		
Description: Adit-001 View into wooded area, with possible Adit site entrance and tank structure.		

Photo No. 2	Date: 13.07.2023	
Southerly view of area west to Adit 287185-001.		
Description: Adit-001 Evidence of ground movements in land adjacent to Adit -001. Unknown if associated with mining works or due to general slope stability.		

Photo No. 3	Date: 13.07.2023	
Northerly view into woodlands at the location of Adit 287185-002.		
Description: Adit-002 Woodland sitting at low elevation, in approximate direction of Adit 287185-002 (based on GPS co-ordinates).		

Photo No. 4	Date: 13.07.2023	
Northerly view into woodlands at the location of Adit 287185-002.		
Description: Adit-002 No associated mine structures were identified within the vicinity of Audit -002, due to dense woodland and the area sitting at a lower elevation. Wooded area fenced-off.		